

Product Discontinuation



PD_052_16

■ Last Order Date:	2016-12-30
■ Last Delivery Date:	2017-06-30

Reason: Streamline the support and manufacturing setup for embedded power products by phasing out the 8051-based TLE983x product family given the availability of the function-compatible TLE984x family.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TLE9831QV	SP000864672	TLE9831QVXUMA1	PG-VQFN-48-22	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9831QV	SP001131398	TLE9831QVXUMA2	PG-VQFN-48-56	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9831QV	SP001391094		PG-VQFN-48-56	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QV	SP001006712	TLE9832QVXUMA2	PG-VQFN-48-22	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QV	SP000442488	TLE9832QVXUMA1	PG-VQFN-48-22	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QV	SP001131898	TLE9832QVXUMA3	PG-VQFN-48-56	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QV	SP001131894		PG-VQFN-48-56	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QX	SP000878786	TLE9832QXXUMA1	PG-VQFN-48-29	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QX	SP001006708	TLE9832QXXUMA2	PG-VQFN-48-29	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QX	SP001131904	TLE9832QXXUMA3	PG-VQFN-48-31	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31
TLE9832QX	SP001131902		PG-VQFN-48-31	TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_052_16

■ Last Order Date:	2016-12-30
■ Last Delivery Date:	2017-06-30

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TLE9832-2QV	SP001131404	TLE98322QVXUMA2	PG-VQFN-48-56	TLE9842-2QX	SP001285608	TLE98422QXXUMA1	PG-VQFN-48-31
TLE9832-2QV	SP001391092	TLE98322QVXUMA3	PG-VQFN-48-56	TLE9842-2QX	SP001285608	TLE98422QXXUMA1	PG-VQFN-48-31
TLE9832-2QV	SP000864682	TLE98322QVXUMA1	PG-VQFN-48-22	TLE9842-2QX	SP001285608	TLE98422QXXUMA1	PG-VQFN-48-31
TLE9832-2QX	SP000878784	TLE98322QXXUMA1	PG-VQFN-48-29	TLE9842-2QX	SP001285608	TLE98422QXXUMA1	PG-VQFN-48-31
TLE9832-2QX	SP001131410		PG-VQFN-48-31	TLE9842-2QX	SP001285608	TLE98422QXXUMA1	PG-VQFN-48-31
TLE9833QX	SP000974880	TLE9833QXXUMA1	PG-VQFN-48-29	TLE9843-2QX	SP001285610	TLE98432QXXUMA1	PG-VQFN-48-31
TLE9833QX	SP001131906	TLE9833QXXUMA2	PG-VQFN-48-31	TLE9843-2QX	SP001285610	TLE98432QXXUMA1	PG-VQFN-48-31
TLE9834QX	SP000977512	TLE9834QXXUMA1	PG-VQFN-48-29	TLE9844-2QX	SP001285612	TLE98442QXXUMA1	PG-VQFN-48-31
TLE9834QX	SP001131912	TLE9834QXXUMA2	PG-VQFN-48-31	TLE9844-2QX	SP001285612	TLE98442QXXUMA1	PG-VQFN-48-31
TLE9835QX	SP000977514	TLE9835QXXUMA1	PG-VQFN-48-29	TLE9845QX	SP001185098	TLE9845QXXUMA1	PG-VQFN-48-31
TLE9835QX	SP001131918		PG-VQFN-48-31	TLE9845QX	SP001185098	TLE9845QXXUMA1	PG-VQFN-48-31

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!