

Doc. No. : PDN210201
Date : Feb 19, 2021

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.															
Parts Affected :															
<table border="1"><thead><tr><th>Part No.</th><th>Package</th></tr></thead><tbody><tr><td>ACDBAT320-HF Thru. ACDBAT3100-HF</td><td>2010</td></tr><tr><td>ACDBN120-HF Thru. ACDBN1100-HF</td><td>1206</td></tr><tr><td>CDBZ310200-HF</td><td>Z3PAK</td></tr><tr><td>CDBZ310200H-HF</td><td>Z3PAK</td></tr><tr><td>CDBZ320200-HF</td><td>Z3PAK</td></tr><tr><td>CDBZ5T30100-HF</td><td>Z5PAK-T</td></tr></tbody></table>		Part No.	Package	ACDBAT320-HF Thru. ACDBAT3100-HF	2010	ACDBN120-HF Thru. ACDBN1100-HF	1206	CDBZ310200-HF	Z3PAK	CDBZ310200H-HF	Z3PAK	CDBZ320200-HF	Z3PAK	CDBZ5T30100-HF	Z5PAK-T
Part No.	Package														
ACDBAT320-HF Thru. ACDBAT3100-HF	2010														
ACDBN120-HF Thru. ACDBN1100-HF	1206														
CDBZ310200-HF	Z3PAK														
CDBZ310200H-HF	Z3PAK														
CDBZ320200-HF	Z3PAK														
CDBZ5T30100-HF	Z5PAK-T														
Reason for Discontinuance :															
Due to the wafer supplier has suddenly shut down, the part listed will be discontinued.															
Alternative Products :															
Please contact sales person or manufacturer's representative.															
Effective Date : Feb 19, 2021															
R&D Dept. Signature :	QA Dept. Signature :														
															