

## Product Obsolescence Notification

Issue Date: 12 APR 2018

Dear Customer,

Broadcom Inc. announces the obsolescence of optocoupler products HCPL-0708 and HCPL-0738. This obsolescence takes effect from notice issue date April 12, 2018.

The obsolescence will affect all associated part options. The replacement products are the closest equivalent but not direct replacement.

Part Affected	Part Type	Alternate Replacement
HCPL-0708	Leaded	No replacement
HCPL-0708#500	Leaded	No replacement
HCPL-0708-000E	Lead-free	ACPL-071L-000E
HCPL-0708-500E	Lead-free	ACPL-071L-500E
HCPL-0708-560E	Lead-free	ACPL-071L-560E
HCPL-0708-560ME	Lead-free	No replacement
HCPL-0738	Leaded	No replacement
HCPL-0738-000E	Lead-free	ACPL-074L-000E
HCPL-0738-00GE	Lead-free	No replacement
HCPL-0738-060	Leaded	No replacement
HCPL-0738-060E	Lead-free	ACPL-074L-060E
HCPL-0738-500	Leaded	No replacement
HCPL-0738-500E	Lead-free	ACPL-074L-500E
HCPL-0738-50GE	Lead-free	No replacement
QCPL-070H-500E	Lead-free	ACPL-071L-500E
QCPL-073H-500E	Lead-free	ACPL-074L-500E

The key milestones are:

1. Formal customer obsolescence notice – April 12, 2018
2. Final customer order date – October 11, 2018
3. Final ship date to customer – April 11, 2019

Please note that Broadcom reserves the rights to limit any last-time buy quantities based on capacity and material availability. Orders will be accepted on a non-returnable basis only.

Broadcom can provide samples of alternate replacement parts for customer evaluation.

If you have any questions about this obsolescence, please do not hesitate to contact your Broadcom sales representative or authorized distributors.

**Broadcom Inc.**  
Isolation Products Division