



Micron Technology, Inc.  
8000 S. Federal Way  
PO Box 6  
Boise, ID United States

## EOL of Specific MCP Part Numbers

PCN: 32447

Published: 2017-08-28

### Revision History:

Revision 1, 2017-08-30: This document supersedes the original PCN #32447, dated 2017-08-28.

Micron part number MTFC32GANALEA-WT — which was mistakenly included in the original publication — has been removed from the Affected Micron Part Number list.

<b>Type:</b>	End of Life
<b>Description:</b>	Specific MCP (Multi-Chip Package) part numbers are going End of Life. Drop in compatible replacement parts are listed below, where applicable.
<b>Reason:</b>	Change in Market Demand
<b>Product Affected:</b>	Multi-Chip Package Products

Affected Micron Part Number Component	Recommended Replacement	Customer Part Number
MT29C2G24MAABAKAKD-5 IT		
MT29C4G96MAZBBCJV-48 IT		
MT29C8G96MAZBBDJV-48 IT		
MT29C8G96MAZBBDKD-48 IT		
MT29RZ1CVCZZHGTN-18 W.85H	MT29RZ1CVCZZHGTN-18 I.85H	

MT29RZ2B2DZZHHTB-18W.88F

MT29RZ2B2DZZHHTB-18I.88F

MT29TZZZ8D5JKETS-107 W.95Q

\*Materials that have been ordered are in **bold**.

---

**Method of Identification:** Marketing Part Number

---

**Micron Sites Affected:** All Sites

---

**Last Purchase Date\*:** 2018-06-29

---

**Last Shipment Date:** 2018-12-31

\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**Micron Confidential and Proprietary Information**

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.