



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M0032

DATE: 17-Apr-2009

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------|-------------------|-------------------------|-----------------|--------------------|------------------------------------|
| Discontinuance | MAX495C/D | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CPA | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CPA+ | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CSA | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CSA+ | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CSA+T | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CSA-T | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CUA | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CUA+ | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495CUA+T | N/A | 15-Oct-2009 | 17-Apr-2011 | The part was not released |
| Discontinuance | MAX495CUA-T | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495EPA | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495EPA+ | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495ESA | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495ESA+ | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495ESA+T | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495ESA-T | MAX4091ASA+ | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495MJA | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |
| Discontinuance | MAX495MJA+ | N/A | 15-Oct-2009 | 17-Apr-2011 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-May-2009