



PRODUCT DISCONTINUATION NOTICE (PDN)

PDN Number: 21015
Date Issued: 9/30/2021
Product(s) Affected:

| Ordering Part Number | Suggested Part Replacement | Functional Equivalent | Pin Compatible | Comments |
|----------------------|----------------------------|-----------------------|----------------|----------------------|
| XRT83VSH38IB-F | - | - | - | No replacement part. |
| XRT83VSH28IB-F | - | - | - | No replacement part. |
| XRT86VL30IV-F | - | - | - | No replacement part. |
| XRT86VL30IV80-F | - | - | - | No replacement part. |
| XRT86VX38AIB256-F | - | - | - | No replacement part. |
| XRT86VX38IB256-F | - | - | - | No replacement part. |

Date Effective: September 29, 2021

Contact: Your local MaxLinear Sales Representative or our Customer Support team by creating a support ticket at <http://www.maxlinear.com/support/createcase>
Phone: 1-760-692-0711

Description and Purpose of Change:

MaxLinear is announcing the discontinuation of the devices noted above effective the date of this PDN due to the closure of the fab line.

Key Dates:

Last Time Buy (LTB): March 29, 2022
Last Time Ship (LTS): September 29, 2022
End of support: September 29, 2022

Response: No response is required to this Product Discontinuation Notice. However, requests for additional data and support should be made within 90 days of this notification. Please address questions to Maxlinear’s Sales and Marketing organization.