



Subject: Product Discontinuation Notification

To whom it may concern,

This is notification that the part numbers listed below will be discontinued by Exar Corporation:

| Ordering Part Number | Suggested Part Replacement | Functional equivalent | Pin Compatible |
|----------------------|----------------------------|-----------------------|----------------|
| SPX29152U5-L         | SPX29152T5-L/TR            | X                     | N/A            |
| SPX29302U5-L         | SPX29302T5-L/TR            | X                     | N/A            |
| SPX1587AU-L          | SPX1587AT-L                | X                     | N/A            |
| SPX1587U-L-3-3       | SPX1587AT-L-3-3            | X                     | N/A            |
| SPX1587U-L-5-0       | SPX1587AT-L-2-5            | X                     | N/A            |
| SPX29502U5-L         | SPX29302T5-L               | X                     | N/A            |

Purchase orders will be accepted as indicated below on a non-cancellable, non-returnable basis provided there is inventory remaining at the time of order placement. \*\* Subject to product availability. No reschedules will be allowed.

|                         |                  |
|-------------------------|------------------|
| <b>Last order date:</b> | July 13, 2016    |
| <b>Last ship date:</b>  | January 13, 2017 |

Please check inventory availability with your distributor or Exar Customer Service Representative before attempting to place an order.

Note to distributors: All LTB purchase orders must be submitted manually.

If you should have any questions regarding this notice, please contact Lisa Bedard via email at [Lisa.Bedard@Exar.com](mailto:Lisa.Bedard@Exar.com) or [customersupport@exar.com](mailto:customersupport@exar.com).