

Product Obsolescence Notification

Issue Date: 19-April-2021

Dear Customer:

Broadcom regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Minimum Order (MOQ)	Suggested Replacement
BCM53202MIPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53549A0IFSBG
BCM53202MKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53549A0KFSBG
BCM53202SKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53549A0KFSBG
BCM5320MIPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53549A0IFSBG
BCM5320MIPB	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53549A0IFSBG
BCM5320MKPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53549A0KFSBG
BCM53212MIPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53548A0IFSBG
BCM53212MKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53548A0KFSBG

BCM53212SC01	53212 chipset	23-May-21	23-Feb-22		#N/A
BCM53212SKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53548A0KFSBG
BCM53212SQ01	BCM53212 Chipset	23-May-21	23-Feb-22		#N/A
BCM53212SR01	BCM53212 Chipset	23-May-21	23-Feb-22		#N/A
BCM5321MIPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53548A0IFSBG
BCM5321MIPB	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53548A0IFSBG
BCM5321MKPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53548A0KFSBG
BCM53242MIPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0IFSBG
BCM53242MKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0KFSBG
BCM53242SAB03	53242 chipset for shenzhen Pho	23-May-21	23-Feb-22		#N/A
BCM53242SKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0KFSBG
BCM53242SS01	53242 chipset	23-May-21	23-Feb-22		#N/A
BCM5324A2KPBG	24+2G L2 Ethernet switch	23-May-21	23-Feb-22		BCM53547A0KFSBG

BCM5324MIPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0IFSBG
BCM5324MKPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0KFSBG
BCM5324MSAV02	24+2G SMB Managed Switch	23-May-21	23-Feb-22		#N/A
BCM5324MSBC01	24+2G SMB Managed Switch	23-May-21	23-Feb-22		#N/A
BCM5324SB00	5324 based chipset	23-May-21	23-Feb-22		#N/A
BCM5324SKPBG	24+2G L2 Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0KFSBG
BCM5324SST02	24+2G WebSmart Switch w/ 1 Cu	23-May-21	23-Feb-22		#N/A
BCM5324SSU01	5324 chipset	23-May-21	23-Feb-22		#N/A
BCM5387IFBG	8 PORT SWITCH SGMII	23-May-21	23-Feb-22		BCM53422A0IFSBG BCM53161XMB1ILFBG
BCM5387KFBG	8 PORT SWITCH SGMII	23-May-21	23-Feb-22		BCM53422A0KFSBG BCM53161XMB1ILFBG
BCM5389IFBG	8 PORT SWITCH SGMII	23-May-21	23-Feb-22		BCM53422A0IFSBG
BCM5389KFBG	8 PORT SWITCH SGMII	23-May-21	23-Feb-22		BCM53422A0KFSBG
BCM5389SAD01	5389 chipset	23-May-21	23-Feb-22		#N/A

BCM5389SV01	5389 chipset	23-May-21	23-Feb-22		#N/A
BCM5389SW01	5389 chipset	23-May-21	23-Feb-22		#N/A
BCM5396IFBGG	16 PORT LAYER 2 GE SWITCH W/SERDES	23-May-21	23-Feb-22		BCM53424A0IFSBG
BCM5396IFBG	16 PORT LAYER 2 GE SWITCH W/SERDES	23-May-21	23-Feb-22		BCM53424A0IFSBG
BCM5396KFBGG	16 PORT LAYER 2 GE SWITCH W/SERDES	23-May-21	23-Feb-22		BCM53424A0KFSBG
BCM5396KFBG	16 PORT LAYER 2 GE SWITCH W/SERDES	23-May-21	23-Feb-22		BCM53424A0KFSBG
BCM5396SD00	5396 based chipset	23-May-21	23-Feb-22		#N/A
BCM5396SR01	BCM5396A0 chipset	23-May-21	23-Feb-22		#N/A
BCM5396SR02	BCM5396A0 chipset	23-May-21	23-Feb-22		#N/A
BCM5396ST02	5396 for Crestron	23-May-21	23-Feb-22		#N/A
BCM5396SV02	5396 chipset	23-May-21	23-Feb-22		#N/A
BCM5396SV03	5396 5482S chipset	23-May-21	23-Feb-22		#N/A
BCM5396SV04	5396 chipset	23-May-21	23-Feb-22		#N/A
BCM5325FIQMG	Ethernet Managed switch	23-May-21	23-Feb-22		#NA



BCM5325FKQMG	Ethernet Managed switch	23-May-21	23-Feb-22		#NA
BCM53262MIPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0IFSBG
BCM53262MKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0KFSBG
BCM53262SKPBG	Ethernet Managed switch	23-May-21	23-Feb-22		BCM53547A0KFSBG

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy (LTB) order date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the Last Time Ship (LTS) date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.